

HID® FARGO® HDP®6600 Printer

Firmware

Release Notes

PLT-04251, A.9
March 2023



Copyright

© 2019 - 2023 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, FARGO, and HDP are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
March 2023	Release notes for firmware version 10.0.25.431.	A.9

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID® FARGO® HDP®6600 Printer Firmware version 10.0.25.431. Included are product features, enhancements, and resolved issues since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

1.2 Resolved issues

- Resolved an issue where an unexpected narrow yellow stripe could be printed on a card under some scenarios. (XS-470, FI#13315)

Note: HID recommends using the HDP6600 with printer driver version 1.0.1.39 and above.

- Resolved an issue where some printers were periodically producing cards that contained a yellowing effect within text printed on the card (when it should be white). Added the **Yellow Panel Edge Alignment** Advanced setting. The available options are -20 to 20 which correspond to the number of pixels to move the image on the panel of the ribbon. A positive value moves the image toward the top of the card while a negative value adjusts the image toward the bottom of the card. A value of 0 means no adjustment is made. (XS-549, FI#13453)
- Resolved an issue where the embedded web page was not displaying these ribbon types correctly: YMCKH, YMCCK, and K Resin. (XS-494, HVPB-314, TTP-13796)
- Resolved an issue where the stretch compensation was not applied consistently to the first panel and to the rest of the panels on a batch job. The Image was not equally centered on the first card compared to the rest of the cards in the batch job. (TTP-14036)

1.3 Known issues

- Some users are reporting that after a firmware upgrade, the **Head Resistance** internal printer setting has been set to 3200 which is incorrect. (FI#12849, XS-134)
- Occurrences of two images being transferred to the same side of the card have been reported. (FI#12138)
- HDP6600 still receives print job after rebooting the printer under a film broken condition. (FI#12344)
- Blush Point** setting on HDP6600 is ineffective. (FI#14382)

Revision history

Date	Description	Revision
March 2023	Release notes for firmware version 10.0.25.431.	A.9
February 2022	Release notes for firmware version 9.0.36.352.	A.8
October 2020	Release notes for firmware version 6.0.12.6020.	A.7
July 2020	Release notes for firmware version 6.0.12.6014.	A.6
July 2020	Release notes for firmware version 6.0.9.6011.	A.5
April 2020	Release notes for firmware version 6.0.9.6011.	A.4
January 2020	Release notes for firmware release 5.0.5.1084.	A.3
July 2019	Release notes for firmware release 3.0.8.1063.	A.2
July 2019	Release notes for firmware release 3.0.7.1056.	A.1
April 2019	Release notes for firmware release 2.0.32.952.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2023 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-04251, Rev. A.9

Part of ASSA ABLOY