



HID® FARGO® HDP®5600

Printer Firmware

Release Notes

Driver Version: 6.9.0
PLT-04725, A.1
May 2020

Powering
Trusted Identities

Copyright

© 2019 - 2020 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, the Chain Design, FARGO, and HDP are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For additional offices around the world, see www.hidglobal.com/contact/corporate-offices.

Americas and Corporate	Asia Pacific
611 Center Ridge Drive Austin, TX 78753 USA Phone: +1 866 607 7339	19/F 625 King's Road North Point, Island East Hong Kong Phone: +852 3160 9833
Europe, Middle East and Africa (EMEA)	Brazil
3 Cae Gwyrdd Green Meadow Springs Cardiff CF15 7AB United Kingdom Phone: +44 (0) 2920 528 500	Condomínio Business Center Av. Ermano Marchetti, 1435 Galpão A2 - CEP 05038-001 Lapa - São Paulo / SP Brazil Phone: +55 11 5514-7100

HID Global Technical Support: www.hidglobal.com/support.

What's new

Date	Description	Revision
May 2020	Release Notes for firmware version 6.9.0.	A.1

A complete list of revisions is available in [Revision history](#).

1 Scope

These release notes provide information on the HID® FARGO® HDP®5600 Printer Firmware version 6.9.0. Included are product enhancements, fixes, known issues, and limitations since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from a HID Global internal tracking system.

2 New features and enhancements

- Added an option to increase the transfer temperature for the first four cards to minimize card chipping (incomplete image transfer). This feature is **OFF** by default to minimize card jams. Contact HID Technical Support for information to enable this feature. (SICPI-10)
- Added the ability to lock/unlock the network settings via the LCD menu. (TTP-5987)

3 Resolved issues

- Resolved an issue where printers would sometimes reset with extreme Ethernet port scanning or excessive Ethernet data traffic.
- Resolved an issue where the **Transfer Cooling Delay** advanced setting had no effect unless the **Apply Additional Film Transfer Layer** box was selected in the driver.

4 Known issues

- Performing firmware upgrades from FARGO Workbench on Windows 10 when not running as an Administrator may result in errors. (SICPI-605)
- If the printer cover is opened when the printer is in the **Paused** state, the printer may not resume printing correctly. (SICPI-606)

Revision history

Date	Description	Revision
May 2020	Release Notes for firmware version 6.9.0.	A.1
February 2019	Release Notes for firmware version 6.8.4.	A.0



Powering Trusted Identities

Americas & Corporate
611 Center Ridge Drive
Austin, TX 78758
USA

Support: 866-607-7339

Asia Pacific 19/F
625 King's Road
North Point
Island East
Hong Kong

Support: 852-3160-9833

Europe, Middle East & Africa
3 Cae Gwyrdd
Green Meadow Springs
Cardiff, CF15 7AB
United Kingdom

Support: +44 (0) 2920 528 500

Brazil
Condomínio Business Center
Av. Ermano Marchetti, 1435
Galpão A2 - CEP 05038-001
Lapa - São Paulo / SP, Brazil
Phone: +55 11 5514-7100

PLT-04725, A.1